


滑走路端安全区域 (RESA) 拡張工事 進捗状況写真 位置図

□RESA用地



滑走路端安全区域（RESA）拡張工事 進捗状況写真【令和6年2月27日】

① 北側から進入灯橋梁



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

② 南側から進入灯橋梁



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

③ 進入灯センターから北側



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】


④ 進入灯センターから南側



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑤ 場周道路から進入灯橋梁



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑥ 進入灯橋梁第3バレットから滑走路側



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑦ 進入灯橋梁第3バレットから北側



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑧ 進入灯橋梁第3バレットから北側下



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑨ 進入灯橋梁第3バレットから南側



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑩ 進入灯橋梁第3バレットから南側下



R3.8.30 【着手前】



R3.10.29




R6.2.1



R6.2.27 【最新】

⑪ 進入灯橋梁第4バレットから北側下



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑫ 進入灯橋梁第4バレットから南側下



R3.8.30 【着手前】



R3.10.29



R6.2.1




R6.2.27 【最新】

⑬ クロスバー北側から滑走路側



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑭ クロスバー南側から滑走路側



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑮ クロスバー南側から進入灯橋梁橋脚



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑯ クロスバー南側から進入灯橋梁橋脚下



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑰ 最下段から下流（治山堰堤）側



R2.10.12 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑱ 治山堰堤からB1盛土側



R2.10.12 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑲ 2段目付近から上段側



R2.10.12 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

⑳ 2段目付近から下段側



R2.10.12 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

②① 市道 立入り禁止柵からB1盛土側



R3.8.11 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

②② 立入り禁止柵内側からB1盛土側



R3.8.11 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

②③ P1橋脚から滑走路側



R3.9.16 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

②④ P1橋脚から南側



R3.9.16 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

㊸ 引き戸付近から南側



R3.10.14 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

㊹ 引き戸付近から滑走路側



R3.10.14 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

㊺ 工事中進入路（第6ゲート付近）



R3.10.14 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

㊻ 工事中進入路（第6ゲート北側）



R3.10.14 【着手前】



R3.10.29




R6.2.1



R6.2.27 【最新】

滑走路端安全区域 (RESA) 拡張工事 進捗状況写真 位置図

□西側用地



㉔ 西側用地 非常時用進入路下段から



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

㉕ 西側用地 非常時用進入路上段から



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

㉖ 西側用地 ストックヤード



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】

㉗ 西側用地 ストックヤード拡大



R3.8.30 【着手前】



R3.10.29



R6.2.1



R6.2.27 【最新】